

BranchMaster™
3/4" Male Sweat Branches
1 1/2" Male Sweat ×
1 1/2" Male Sweat Trunk

- Branches are 3" on-center
- 1 1/2" Type L copper trunk
- Press-fitting compatible



More Radiant Heat Manifolds are within F1807 PEX
 See BranchMaster™ Manifold information p 66

Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
6796L-12333	12	3/4" male sweat	B	1	5



SUPPLY

DRAINAGE

BranchMaster™
3/4" Male Sweat Branches
2" Male Sweat × 2" Male Sweat Trunk

- Branches are 3" on-center
- 2" Type L copper trunk
- Press-fitting compatible



More Radiant Heat Manifolds are within F1807 PEX
 See BranchMaster™ Manifold information p 66

Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
6797L-12333	12	3/4" male sweat	B	1	4



SUPPORT

APPENDIX

BranchMaster™
3/4" Female Sweat Branches
1 1/4" Male Sweat ×
1 1/4" Male Sweat Trunk

- Branches are 4" on-center
- 1 1/4" Type L copper trunk
- Press-fitting compatible



More Radiant Heat Manifolds are within F1807 PEX
 See BranchMaster™ Manifold information p 66

Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
67745L-08334	8	3/4" female sweat	B	1	5

