

PowerPEX™

1/2" F1807 PEX Branches

3/4" F1807 PEX × Spin Closed Trunk

- 1" Type L copper trunk
- Branches are 2" on-center
- Great as a secondary manifold



Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
672X0390	3	1/2" F1807	B	25	25
672X0390PK	3	1/2" F1807	C*	5	5
672X0490	4	1/2" F1807	B	25	25
672X0490PK	4	1/2" F1807	C*	5	5
672X0590	5	1/2" F1807	B	25	25
672X0690	6	1/2" F1807	B	25	25
672X0690PK	6	1/2" F1807	C*	5	5
672X0790	7	1/2" F1807	B	25	25
672X0890	8	1/2" F1807	B	25	25
672X0990	9	1/2" F1807	B	25	25
672X1090	10	1/2" F1807	B	25	25
672X1290	12	1/2" F1807	B	25	25




PowerPEX™

1/2" F1807 PEX Ball Valve Branches

3/4" F1807 PEX × Spin Closed Trunk

- 1" Type L copper trunk
- Branches are 2" on-center



Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
672XV0490	4	1/2" F1807 ball valve	B	1	10
672XV0490PK	4	1/2" F1807 ball valve	C*	5	5
672XV0590	5	1/2" F1807 ball valve	B	1	10
672XV0690	6	1/2" F1807 ball valve	B	1	10

PowerPEX™

1/2" F1807 PEX Branches

3/4" F1807 PEX × Spin Closed Extended Trunk

- 1" Type L copper trunk
- Branches are 2" on-center
- Extended ends can be easily converted to 1" male sweat by cutting off the reduction or spin closed end, leaving 5" from PEX branch



Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
672X0490EE	4	1/2" F1807	B	10	10
672X0690EE	6	1/2" F1807	B	10	10

