


**PowerPEX™**

**1/2" F1807 PEX Ball Valve Branches**  
**3/4" Male Sweat ×**  
**3/4" Female Sweat Trunk**

- 3/4" Type L copper trunk
- Branches are 2" on-center



Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
672XV3L-0431PK	4	1/2" F1807 ball valve	C*	5	5

**PowerPEX™**

**1/2" F1807 PEX Branches**  
**3/4" Male Sweat × Spin Closed Trunk**

- 1" Type L copper trunk
- 3/4" male sweat connection provides flexibility
- Branches are 2" on-center



Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
672X0330	3	1/2" F1807	B	25	25
672X0430	4	1/2" F1807	B	25	25
672X0630	6	1/2" F1807	B	25	25
672X0830	8	1/2" F1807	B	25	25
672X0930	9	1/2" F1807	B	25	25
672X1230	12	1/2" F1807	B	25	25



**PowerPEX™**

**1/2" F1807 PEX Branches**  
**1" Male Sweat × 1" Male Sweat Trunk**

- 1" Type L copper trunk
- Branches are 2" on-center



Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
672X0444	4	1/2" F1807	B	25	25
672X0644	6	1/2" F1807	B	25	25
672X0844	8	1/2" F1807	B	25	25
672X1244	12	1/2" F1807	B	25	25



SUPPLY

DRAINAGE

SUPPORT

APPENDIX