

SUPPLY

DRAINAGE



**PowerPEX™**

**1/2" F1807 PEX Branches**

**1" Male Sweat × 1" Female Sweat Trunk**

- 1" Type L copper trunk
- Branches are 2" on-center



Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
672X0441PK	4	1/2" F1807	C*	5	5

SUPPORT

APPENDIX



**PowerPEX™**

**1/2" F1807 PEX Branches**

**1" Male Sweat × 1" Female Sweat Trunk**

- 1" Type L copper trunk
- Branches are 2" on-center (unless noted)
- Brazed branches




Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
672X0242	2	1/2" F1807	B	1	10
672X0342	3	1/2" F1807	B	1	10
672X0442	4	1/2" F1807	B	1	10
672X4L-1131B3	11	1/2" F1807, 3" O.C.	B	5	5

**PowerPEX™**

**1/2" F1807 PEX Ball Valve Branches**

**1" Male Sweat × 1" Female Sweat Trunk**

- 1" Type L copper trunk
- Branches are 2" on-center (unless noted)



Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
672XV0242	2	1/2" F1807 ball valve	B	1	10
672XV0342	3	1/2" F1807 ball valve	B	1	10
672XV0431PK	4	1/2" F1807 ball valve	C*	5	5
672XV0442	4	1/2" F1807 ball valve	B	1	10
672XV4L-11313	11	1/2" F1807 ball valve, 3" O.C.	B	1	5