


Scotch-Brite™ Discs: Clean and Strip

Scotch-Brite™ Clean and Strip XT Pro Discs

- Quickly removes rust, paint, mill scale and coatings from metal
- High-strength fiber resists chunking and performs well on edges
- High conformability provides a larger contact patch for faster removal rates
- Silicon carbide mineral cuts aggressively and leaves a fine finish



| UPC | Dia x AH | Grade | Max RPM | Min/Case |
|-------------------------|-----------------|-------|---------|----------|
| T27 | | | | |
| 638060-21659-0 | 4" x 1/4" | S XCS | 9,000 | 25 |
| 638060-05586-1 | 4-1/2" x 7/8" | S XCS | 13,300 | 10 |
| 638060-21661-3 | 6" x 1/2" | S XCS | 4,000 | 15 |
| 638060-29938-8 | 7" x 3-1/8" | S XCS | 3,600 | 15 |
| 638060-05587-8 | 7" x 7/8" | S XCS | 8,600 | 5 |
| T27 Quick Change | | | | |
| 638060-05574-8 | 4-1/2" x 5/8-11 | S XCS | 13,300 | 10 |
| 638060-29931-9 | 5" x 5/8-11 | S XCS | 12,000 | 10 |
| 076308-45481-4 | 7" x 5/8-11 | S XCS | 8,600 | 5 |
| TN Quick Change | | | | |
| 638060-05588-5 | 4-1/2" x 5/8-11 | S XCS | 13,300 | 10 |
| 638060-05589-2 | 7" x 5/8-11 | S XCS | 8,600 | 5 |
| Roloc™ TR | | | | |
| 638060-21538-8 | 2" x NH | S XCS | 18,000 | 10/60 |
| 638060-21540-1 | 3" x NH | S XCS | 15,000 | 10 |
| 638060-21541-8 | 3" x NH | S XCS | 15,000 | 10/40 |
| 638060-21542-5 | 4" x NH | S XCS | 11,000 | 10/40 |

Scotch-Brite™ Clean and Strip XT Pro Extra Cut Discs

- Quickly removes heavy rust, thick paint, corrosion and cleans welds
- Aluminum oxide mineral aggressively removes top layer and cleans to the bare metal underneath
- High conformability provides a larger contact patch for faster removal rates
- High-strength fiber resists chunking and performs well on edges



| UPC | Dia x AH | Grade | Max RPM | Min/Case |
|-------------------------|-----------------|-------|---------|----------|
| T27 | | | | |
| 638060-21663-7 | 4" x 1/4" | A XCS | 9,000 | 25 |
| 638060-21032-1 | 4-1/2" x 7/8" | A XCS | 13,300 | 10 |
| 638060-21664-4 | 6" x 1/2" | A XCS | 4,000 | 15 |
| 638060-29940-1 | 7" x 3-1/8" | A XCS | 3,600 | 15 |
| 638060-21036-9 | 7" x 7/8" | A XCS | 8,600 | 5 |
| T27 Quick Change | | | | |
| 638060-21050-5 | 4-1/2" x 5/8-11 | A XCS | 13,300 | 10 |
| 638060-29936-4 | 5" x 5/8-11 | A XCS | 12,000 | 10 |
| 638060-21055-0 | 7" x 5/8-11 | A XCS | 8,600 | 5 |
| TN Quick Change | | | | |
| 638060-21037-6 | 4-1/2" x 5/8-11 | A XCS | 13,300 | 10 |
| 638060-21039-0 | 7" x 5/8-11 | A XCS | 8,600 | 5 |
| Roloc™ TR | | | | |
| 638060-21543-2 | 2" x NH | A XCS | 18,000 | 10/60 |
| 638060-21544-9 | 3" x NH | A XCS | 15,000 | 10 |
| 638060-21545-6 | 3" x NH | A XCS | 15,000 | 10/40 |
| 638060-21546-3 | 4" x NH | A XCS | 11,000 | 10/40 |