






3/8" One Way Shut-Off – 4 & B Series

(Industrial Interchange)

4 & B Series 3/8" 1-Way Automatic Sockets

Female Thread		Part No.	Brand	FPT	Description
		FM4004	F	1/4"	Brass
		B-3BF2-B	B		
		SL4004	F		Sleeve Lock Brass
		B-3BF2-B-SL	B		
		FM4204	F	3/8"	Brass
		B-3BF3-B	B		
		SL4204	F		Sleeve Lock, Brass
		B-3BF3-B-SL	B		
		FM4204H	F		For Heat, Viton Seal
		FM4204W	F	For Water, Brass/SS, Buna-N Seal	
		FM4404	F	1/2"	Brass
		B-3BF4-B	B		
		SL4404	F		Sleeve Lock, Brass
		B-3BF4-B-SL	B		
FM4404S	F	For Steam, Brass/SS, EPDM Seal			
FM4404W	F	For Water, Brass/SS, Buna-N Seal			

Male Thread		Part No.	Brand	MPT	Description
		FM4104	F	1/4"	Brass
		B-3BM2-B	B		
		SL4104	F		Sleeve Lock, Brass
		B-3BM2-B-SL	B		
		FM4104S	F	For Steam, Brass/SS, EPDM Seal	
		FM4104W	F	For Water, Brass/SS, Buna-N Seal	
		FM4304	F	3/8"	Brass
		B-3BM3-B	B		
		SL4304	F		Sleeve Lock, Brass
		B-3BM3-B-SL	B		
		FM4304S	F		For Steam, Brass/SS, EPDM Seal
		FM4304W	F	For Water, Brass/SS, Buna-N Seal	
		FM4504	F	1/2"	Brass
		B-3BM4-B	B		
SL4504	F	Sleeve Lock, Brass			
B-3BM4-B-SL	B				
FM4504S	F	For Steam, Brass/SS, EPDM Seal			
FM4504W	F	For Water, Brass/SS, Buna-N Seal			

Hose Stem		Part No.	Brand	I.D.	Description
		FM4604	F	1/4"	Brass
		B-3BS2-B	B		
		SL4604	F		Sleeve Lock, Brass
		B-3BS2-B-SL	B		
		FM4704	F	5/16"	Brass
		B-3BS5-B	B		
		SL4704	F		Sleeve Lock, Brass
		B-3BS5-B-SL	B		
		FM4804	F	3/8"	Brass
		B-3BS3-B	B		
		SL4804	F		Sleeve Lock, Brass
		B-3BS3-B-SL	B		
		FM4804H	F		For Heat, Viton Seal
		FM4804W	F	For Water, Brass/SS, Buna-N Seal	
		FM4904	F	1/2"	Brass
		B-3BS4-B	B		
		SL4904	F		Sleeve Lock, Brass
		B-3BS4-B-SL	B		
		FM4904W	F		For Water, Brass/SS, Buna-N Seal

Requires Hose Clamp (See page 200 for typical hose clamps)

Brand - Designates **F**=Foster or **B**=Breco Part

See page 380 for full size templates



WARNING: These products can expose you to chemicals including lead, which is known to the State of California to cause cancer, and which is known to cause birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov.