

Pipe Bore Adapter

- Extruded flexible PVC adapter connects any 6" nominal bore to 4" iron or plastic pipe



880

SUPPLY

DRAINAGE


SUPPORT

Item No	Description	Pkg	Min Qty	Case Qty
880	4" to 6" rolling o-ring adapter	B	25	25


Condensate Trap

P Trap or Running Trap

- One piece ¾" Sch. 40 PVC trap saves fittings and job costs when trapping condensate lines



867-30



867-35

APPENDIX

Item No	Description	Dimensions		Pkg	Min Qty	Case Qty
		A	B			
867-30	P trap	8"	2½"	B	50	50
867-35	Running trap	10¾"	2"	B	25	25
867-30PK	P trap	8"	2½"	C*	25	25
867-35PK	Running trap	10¾"	2"	C*	25	25