


SUPPLY

DRAINAGE

SUPPORT

APPENDIX




BranchMaster™

**1/2" MIP/Female Sweat
Balancing Valve Branches**

1" Male Sweat × 1" Female Sweat Trunk

- 1" Type L copper trunk
- Branches are 2" on-center
- Brazed branches
- Perfect for hydronic applications

Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
675-B20242	2	1/2" MIP/female sweat balancing valve	B	1	12
675-B20342	3	1/2" MIP/female sweat balancing valve	B	1	10
675-B20442	4	1/2" MIP/female sweat balancing valve	B	1	10



BranchMaster™

1/2" MIP Branches

1" Male Sweat × 1" Male Sweat Trunk

- 1" Type L copper trunk
- Branches are 2" on-center
- Brazed branches
- Perfect for hydronic applications

Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
675-20244	2	1/2" MIP	B	10	10
675-20344	3	1/2" MIP	B	10	10
675-20444	4	1/2" MIP	B	10	10
675-20544	5	1/2" MIP	B	10	10



BranchMaster™

3/4" Male Sweat Branches

**1 1/4" Male Sweat ×
1 1/4" Male Sweat Trunk**

- Branches are 3" on-center
- 1 1/4" Type L copper trunk
- Press-fitting compatible



Item No	Branch Qty	Branches	Pkg	Min Qty	Case Qty
6795L-12333	12	3/4" male sweat	B	1	5