


Viega ProPress 1/2" to 2"

Dimensional documentation (inches)



Bronze Adapter P x MPT - Model 2911ZL

Part No	Size		A (in)	L (in)
	1	2		
79210	1/2"	3/8" MPT	0.77	1.59
79215	1/2"	1/2" MPT	0.89	1.71
79220	1/2"	3/4" MPT	1.00	1.83
79225	3/4"	1/2" MPT	1.02	1.93
79230	3/4"	3/4" MPT	1.02	1.93
79235	3/4"	1" MPT	1.18	2.09
79240	1"	3/4" MPT	1.18	2.09
79245	1"	1" MPT	1.26	2.17
79250	1"	1 1/4" MPT	1.54	2.44
79255	1 1/4"	1" MPT	1.22	2.24
79260	1 1/4"	1 1/4" MPT	1.34	2.36
79265	1 1/4"	1 1/2" MPT	1.48	2.50
79270	1 1/2"	1 1/4" MPT	1.34	2.76
79275	1 1/2"	1 1/2" MPT	1.28	2.70
79280	1 1/2"	2" MPT	1.65	3.07
79285	2"	1 1/2" MPT	1.54	3.11
79290	2"	2" MPT	1.50	3.07

Bronze Adapter P x MPT - Model 2911

Part No	Size		A (in)	L (in)
	1	2		
77812	1/2"	3/8" MPT	0.97	1.71
77817	1/2"	1/2" MPT	1.12	1.87
77822	1/2"	3/4" MPT	1.22	1.97
77827	3/4"	1/2" MPT	1.18	2.09
77832	3/4"	3/4" MPT	1.18	2.09
22348	3/4"	1" MPT	1.42	2.32
77837	1"	3/4" MPT	1.32	2.22
77842	1"	1" MPT	1.46	2.36
77847	1"	1 1/4" MPT	1.73	2.64
77852	1 1/4"	1" MPT	1.42	2.44
77857	1 1/4"	1 1/4" MPT	1.54	2.56
77862	1 1/4"	1 1/2" MPT	1.65	2.68
77867	1 1/2"	1 1/4" MPT	1.54	2.95
77872	1 1/2"	1 1/2" MPT	1.54	2.95
22343	1 1/2"	2" MPT	1.83	3.25
22338	2"	1 1/2" MPT	1.68	3.25
77877	2"	2" MPT	1.67	3.25